

TO BE FILLED BY THE INSPECTING OFFICER
TO BE FILLED BY THE INSPECTING OFFICER (ASSISTANT ENGINEER)

- 1 Name of School : Sree Narayana Public School, Kollengode Sub Dist, Palakkad
- 2 Name of Officer : SUDHA S
- 3 Location : Kollengode
- 4 Period for which Certificate is issued : 2026-2027
- 5 Types of building :- RCC Roofed Building

Fitness Mentioned Below

- Building No. 10/846
- GF : 6.08 m x 5.94 m x 3.60 m - 2 Class Rooms
: 5.94 m x 5.94 m x 3.60 m - 1 Class Room
: 6.08 m x 24.40 m x 3.60 m - 1 Conference Room
- FF : 6.08 m x 5.94 m x 3.60 m - 2 Class Rooms
: 5.94 m x 5.94 m x 3.60 m - 1 Class Room
: 6.08 m x 24.40 m x 3.60 m - 1 Conference Room
: 9.02 m x 6.00 m x 3.60 m - 2 Class Rooms
: 9.45 m x 6.00 m x 3.60 m - 1 Class Room
- SF : 6.08 m x 5.94 m x 3.60 m - 2 Class Rooms
: 5.94 m x 5.94 m x 3.30 m - 1 Class Room
: 8.08 m x 27.49 m x 3.60 m - 1 Libraray Room
: 9.02 m x 6.00 m x 3.60 m - 2 Class Rooms
: 9.45 m x 6.00 m x 3.60 m - 1 Class Room
- Building No. 10/847 : 6.00 m x 8.92 m x 3.60 m - 4 Class Rooms
- Building No. 10/848 : 6.40 m x 6.12 m x 3.60 m - 4 Class Rooms GF, FF
: 6.40 m x 2.94 m x 3.60 m - 1 staff rooms GF, FF
- SF : 6.40 m x 15.66 m x 3.60 m - Hall
: 6.40 m x 15.09 m x 3.60 m - Class Room
- Building No. 10/195, 198, 199
- GF : 9.02 m x 6.00 m x 3.60m class Room
: 3.00 m x 6.00 m x 3.60 m - Stair Room
: 9.45 m x 6.00m x 3.60 m - Stage
: 9.28 m x 6.00 m x 3.60 m - Class room
: 6.12 m x 9.55m x 3.60m - Chemistry Lab
: 6.12 m x 6.21 m x 3.60 m - Physics Lab
: 6.12 m x 6.33 m x 3.60 m - Maths Lab
: 6.12 m x 3.00 m x 3.60 m - Stair Room
: 6.12 m x 8.42 m x 3.60 m - Class Room
: 6.12 m x 8.30 m x 3.60 m - Office Room
: 6.12 m x 8.42 m x 3.60 m - Pricipal Room
: 6.12 m x 8.42 m x 3.60 m - Stair Room
: 6.12 m x 6.15 m x 3.60 m - Store Room
: 6.12 m x 6.15 m x 3.60 m - Office Room
: 6.12 m x 6.15 m x 3.60 m - Office Room
: 8.78 m x 9.45 m x 3.60m - Toilet Area

FF : 6.12 m x 6.33 m x 3.60 m -Class Room
 : 6.12 m x 6.21 m x 3.60 m -Class Room
 : 6.12 m x 6.21 m x 3.60 m -Class Room
 : 6.12 m x 6.33 m x 3.60 m -Class Room
 : 6.12 m x 3.00 m x 3.60 m -Stair Room
 : 6.12.m x 8.42 m x 3.60 m -Class Room
 : 6.12.m x 8.30 m x 3.60 m -Class Room
 : 6.12.m x 8.42 m x 3.60 m -Class Room
 : 6.12 m x 3.60 m x 3.60 m -Stair Room
 : 6.12 m x 6.15 m x 3.60 m -Class Room
 : 6.12 m x 6.03 m x 3.60 m -Class Room
 : 6.12 m x 6.15 m x 3.60 m -Class Room
 : 8.78 m x 9.45 m x 3.60m -Toilet Area

SF : 6.12 m x 6.33 m x 3.60 m -Class Room
 : 6.12 m x 6.21 m x 3.60 m -Class Room
 : 6.12 m x 6.21 m x 3.60 m -Class Room
 : 6.12 m x 6.33 m x 3.60 m -Class Room
 : 6.12 m x 3.00 m x 3.60 m -Stair Room
 : 6.12.m x 8.42 m x 3.60 m -Class Room
 : 6.12.m x 8.30 m x 3.60 m -Class Room
 : 6.12.m x 8.42 m x 3.60 m -Class Room
 : 6.12 m x 3.60 m x 3.60 m -Stair Room
 : 6.12 m x 6.15 m x 3.60 m -Class Room
 : 6.12 m x 6.03 m x 3.60 m -Class Room
 : 6.12 m x 6.15 m x 3.60 m -Class Room
 : 8.78 m x 9.45 m x 3.60m -Toilet Area

- 6 Name of defect if any : Nil
 (a) Foundation and basement : Nil
 (b) Superstructure : Nil
 (c) Doors and windows : Nil
 (d) Wood work wrought and put : Nil
 (e) Roof : Nil
 (f) Flooring : Nil
 (g) Miscellaneous : Nil

noticed which will render
 7 the building unsafe if any
 manner : Nil

8 Whether maintenance work
 have been done properly : Yes

9 Whether structure is sound Yes, Structure is sound for conducting classes under normal weather
 for conducting classes : conditions

Note (i) The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure to flood etc.

Note(2) Any additional observation if deemed necessary for the certificate may be furnished separately with the certificate.

Certified that the school was inspected by me on 30-05-2026 and found fit to conduct classes for the period 2026-27 Academic year under normal weather conditions for the reason stated above with following conditions.

1. This certificate is applicable only to safety related to civil construction. Separate certificates for fire safety and safety of electrical installations, electrical lines/conduits shall be obtained from the concerned departments.
2. Maintenance of the school premises should be done periodically. The inspecting officer is not liable for any unfortunate accidents in the school premises due to lack of security or periodic maintenance.
3. This certificate is only for the structural safety of the classrooms mentioned in this certificate. It does not cover safety in laboratories, kitchens, etc.
4. For any new construction in the school compound, it should be intimated and a permit should be obtained from LSGI. Safety measures such as barricades must be ensured.
5. Internal wiring of the school should be verified by a registered /Approved Electrician before conducting classes.

Place :Kollengode

Date : 30/05/2026

Signature:

Designation:



SUDHA. S
PEN.No: 667472
ASSISTANT ENGINEER
Local Self Government Department
Kollengode Gramapanchayat

